#### **DEPARTMENT OF TRANSPORTATION**

**DIVISION OF ENGINEERING SERVICES** Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

99.15 File #:

# SOURCE INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** SIR-000573 Address: 333 Burma Road **Date Inspected:** 25-Apr-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1830 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

**Contractor:** BAOSTEEL **Location:** Puxi, Shanghai

**Quality Control Contact:** Mr. Pei **Quality Control Present:** Yes No

**Material transfer:** Yes N/A **Sampled Items:** Yes No N/A No **Stock Transfer:** N/A N/A Yes No **OK to Cut:** Yes No **Rebar Test Witness:** Yes Yes N/A No N/A **Delayed/Cancelled:** No

Other: Witness mechanical and related testing of galvanized wire at BAOSTEEL.

**Bridge No:** 34-0006 Galvanized Wire for the SAS Main Cable **Component:** 

**Bid Item:** Lot No: B216 66

#### **Summary of Items Observed:**

This QA Inspector witnessed tensile tests on 35 cut lengths from one end of 224 coils of galvanized wire. The coil numbers and test data are recorded on a separate electronic spreadsheet. Also witnessed were tests for Tortional Ductility, Zinc Coating Adhesion for 3 of the 35 coil specimens. Tortional Ductility and Zinc Coating Adhesion tests were also performed on 3 additional test specimens which were not tensile tested today. Those 3 coil specimens were cut from coils 661, 671 and 711. All test results conformed to contract requirements.





### **Summary of Conversations:**

# SOURCE INSPECTION REPORT

(Continued Page 2 of 2)

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact, who represents the Office of Structural Materials for your project.

Inspected By:	Franco, Charlie	Quality Assurance Inspector
Reviewed By:	Clifford, William	QA Reviewer